

# Compression fitting M8x1, M10x1, M12x1, 1/8"NPT 1/8"BSP, 1/4"NPT, 1/4"BSP, 3/8"BSP/NPT

## Compression fitting

<b>Material</b>	Stainless steel Double stainless steel ferrule. After fixation the fitting is no longer adjustable
<b>Working temperature</b>	Max. 500°C
<b>Working pressure</b>	Max. 40bar
<b>Process connection</b>	M8x1, M10x1 and M12x1 1/8"BSP (G1/8"), 1/4"BSP (G1/4"), 1/8"NPT. 1/4NPT, 3/8"BSP/NPT



## Options

Other materials  
Other process connections

## Ordering code

\*This datasheet is purely indicative, build-up of model code may vary from this datasheet.

